

THE NETHERLANDS  
(N E D E R L A N D)

## COMMUNICATION



Concerning<sup>(1)</sup>:

- approval granted
- ~~approval extended~~
- ~~approval refused~~
- ~~approval withdrawn~~
- ~~production definitely discontinued~~

of a type of ~~electrical~~/electronic sub-assembly<sup>(1)</sup> with regard to Regulation number 10.**Approval number: E4\*10R05/01\*4432\*00**

1. Make (trade name of manufacturer) : MASTERVOLT
2. Type and general commercial description(s) : MLI Ultra
3. Means of identification of type, if marked on the ~~vehicle/component~~ separate technical unit<sup>(1)</sup> : MLI Ultra 24/5500,  
MLI Ultra 12/5500  
(MLI Ultra ??/?????)
- 3.1. Location of that marking : On the top side.
4. Category of vehicle : M, M1, M2, M3, N, N1, N2, N3, O, O1, O2, O3,  
O4, G  
(All categories)
5. Name and address of manufacturer : Mastervolt B.V.  
Snijdersbergweg 93  
1105 AN Amsterdam Z.O.  
The Netherlands
6. In the case of components and separate technical units, location and method of affixing of the approval mark : Sticker (identification label) on the top side.

**Approval number: E4\*10R05/01\*4432\*00**

7. Address(es) of assembly plant(s) : --Confidential Information--
8. Additional information (where applicable) : see Appendix below
9. Technical service responsible for carrying out the tests : DARE!! Measurements  
Vijzelmolenlaan 7  
3447 GX Woerden  
The Netherlands
10. Date of test report : 2019 September, 18
11. Number of test report : 19C00093RPT01
12. Remarks (if any) : see Appendix
13. Place : Zoetermeer
14. Date : 05 November 2019
15. Signature :   

16. The index to the information package lodged with the approval authority, which may be obtained on request, is attached.
17. Reasons for extension : --

---

<sup>(1)</sup> Strike out what does not apply.